# Data Management Software CL-S10w Installation Guide





#### **Safety Warning**

Please read this manual and the instrument and computer manual carefully beforehand and use the software properly and safely.

#### Official name of the applications used in this manual

(Notation in the main text) (Official name)

Windows, Windows XP Microsoft® Windows® XP Professional Operating System Windows, Windows 7 Microsoft® Windows® 7 Professional Operating System

Windows, Windows 8 Microsoft® Windows® 8 Pro Operating System

Excel Microsoft® Excel®

#### Notes about the text

- Unauthorized reproduction in whole or part of this manual is prohibited.
- The contents of this document may change without notice.
- Every effort is made to ensure the information in this text is correct, but in the event of doubt, error or omission, please contact the vendor where you made your purchase.
- No responsibility shall be bore in the event of accidents related to the use of this product not in accordance with the instructions, notwithstanding the above mentioned.

#### **About the registered Trademark**

Microsoft, Windows, Windows XP, Windows 7, Windows 8, Excel are U.S. registered trademarks of Microsoft corporation in the U.S. and other countries.

#### Software Terms of Use

The terms of use for this software is shown in the end user agreement dialog during online installation. Installation will start only if the user agrees to the agreement.

#### Notes in use

- This software is an application running on the Windows XP, Windows 7 or Windows 8. Neither OS includes this software.
- Before you install this software, one of the above OS must be installed in the PC.
- This software is an Add-Ins software for Excel 2003, Excel 2007, Excel 2010 or Excel 2013.
   None of the Excel includes this software.
- Before you install this software, one of the above Excel must be installed in the PC.
- Please set and insert the CD-ROM smoothly and correctly into the CD-ROM drive.
- Please do not stain or scratch the recording surface of the CD-ROM as it will lead to reading errors.
- Please avoid extreme temperature changes and condensation.
- Do not leave in direct sunlight or near areas with high temperatures such as heaters.

- Please do not apply force or drop the CD-ROM.
- Please do not apply water, alcohol or thinner etc to the CD-ROM.
- Please remove the CD-ROM only when the PC is switched on.

#### Note about the storage

- Please store the CD-ROM in its case after use and take good care of it.
- Please do not store in direct sunlight or near areas with high temperatures such as heaters.
- Please do not store the CD-ROM in areas of high humidity.

#### Method of disposal

 Please dispose of this product according to the rules and regulations of the governing body of the respective region.

#### **Package Contents**

- One Installation CD-ROM of Data Management software CL-S10w
   (CL-10w Setup, CL-S10w Instruction Manual, CL-500A SDK, CL-500A SDK Reference Manual)
- Installation guide (This document)
- Service Guide

This instruction guide is also installed in PDF form with a shortcut in the start menu during the software installation.

\* If you are using Windows 8, right-click on the start screen and select "All applications" at the lower right of the screen.

To read the manual, go to <Start Menu -> All programs -> KONICAMINOLTA -> CL-S10w -> CL-S10w Manual> PDF file. The installation CD-ROM also contains other language versions of the instruction manual in PDF format. You will need the Adobe Reader® from Adobe Corporation. The latest Adobe Reader® could be downloaded for free from the Adobe website. Also, it is possible to use the Adobe Reader® installer included with the installation CD-ROM for installation.

(Example) When the CD-Rom is in E drive E: \Adobe Reader \EN

#### **System Requirements**

(Conditions of Use)	OS	Windows XP Professional SP3 32 bit,
		Windows XP Professional SP2 64 bit,
		Windows 7 Professional 32 bit,
		Windows 7 Professional 64 bit,
		Windows 8 Pro 32 bit,
		Windows 8 Pro 64 bit
		(The Japanese, English, Chinese (Tradit

(The Japanese, English, Chinese (Traditional),
Chinese (Simplified) version of the above OS)
Application Software Excel 2003 (When using Windows XP OS)

Application Soπware Excel 2003 (When using Windows XP OS)

Excel 2007, Excel 2010 (When using Windows 7 OS)
Excel 2010 32 bit, Excel 2013 32 bit (When using Windows 8 OS)

(Control target) Photometer CL-500A, CL-200, CL-200A

(Language) Display language Japanese, English, Chinese (Simplified) (Select any one


during installation)

#### **Contents**

Installation procedures			4
When using Windows XP, Excel 2003	1. 2. 3.	InstallationInstallation of the device driverUninstallation of CL-S10w(Before version up)	8
When using Windows 7, Excel 2007	1. 2. 3.	Installation of the device driver Uninstallation of CL-S10w (Before version up)	16
When using Windows 8, Excel 2013	1. 2. 3.	Installation	27
About the template	1. 2. 3. 4. 5. 6. 7.	Measurement values trend	32 33 33 34

## **Installation procedures**

This software is supplied in CD-ROM form, therefore a CD-ROM drive is required for installation. You need to log in as a user with administrator privileges to install this software.



If an older version of this software has been installed in the PC, uninstall the older version before installing the latest version.

Installation of CL-S10w from the CD-ROM.

Set the Add-Ins in Excel.

The installation procedure differs slightly depending on which version of Excel you are using; Excel 2003, 2007, 2010 or 2013.

Install the device driver for connecting the instrument to a USB port of the PC.

The installation procedure differs depending on which version of Windows you are using; Windows XP, 7 or 8.

Please see the instruction manual for the usage of CL-S10w. It is possible to access the instruction manual from the Start menu (Adobe Reader® is required separately). <Start -> All Programs -> KONICAMINOLTA -> CL-S10w -> CL-S10w Manual>

## When using Windows XP, Excel 2003

#### 1. Installation

- Start Windows.
- 2 Set the CL-S10w CD-ROM in the CD-ROM drive. The installation program should start up automatically. Please double-click on the Setup.exe icon if the installation does not start automatically.
- Select a language from the language dialog box and click OK.

  'Chinese' is in simplified form.

  When using Traditional Chinese
  OS, please select the 'English'.

  We shall proceed and explain with the 'English' hence on.
- The wizard screen will appear and click Next.

Read the License Agreement and select (a) 'I accept the terms in the license agreement' if you agree to it and click Next .









## 6 Check the destination folder to install to and click Next.


The destination folder can be changed. Please remember the path of the destination folder as it is necessary during the Excel Add-Ins setup.

7 Click Install .
File copy will begin.



Next add CL-S10w into Excel Add-Ins. Start Excel 2003 and choose 'Add-Ins' from 'Tools' in the menu bar.










10 Click Browse from the Add-Ins setting menu.



Select the destination folder where CL-S10w is installed and select the CL-S10w.xla (the file extension might not be shown in some cases) and click OK.


(Example) C:\Program Files \KONICAMINOLTA\CL-S10w

12 Check the ☑ 'CI-S10w' added in the Add-Ins setting menu and click OK.





13 "CL-S10W" was added to the menu bar in Excel 2003.



#### 2. Installation of the device driver

Connecting the instrument to a USB port of the PC requires the device driver to be installed. Please follow the steps below.

#### For CL-500A

## Connect the instrument to a USB port of the PC.

Device driver installation will begin.

## **2** Wait for a while until the following message appears.

Two kinds of device drivers for CL-500A will be installed.

The installation may take several minutes.

Do not turn off the power of CL-500A or pull out the USB cable until the installation is complete.

#### Use the following procedure to heck that the device drivers are properly installed.

Select "Control panel" from the start menu and select "System".

The select "Device manager" from the "Hardware" tab. The following screen will appear.


On this screen, make sure that "USB Composite Device" has properly been installed.

If the installation fails, the "USB Composite Device" may not be displayed on the screen or, even if the "USB Composite Device" is displayed, some devices may be located under the "Other devices" directory as shown in the figure below.

In such a case, uninstall the "USB Composite Device" and some devices under the "Other devices" directory; then perform the installation again from step 1.

The above installation is completed.









#### For CL-200A

With the CL-S10w installation CD-ROM inserted in the PC, connect the instrument to a USB port of the PC.

Select **( )** 'No, not this time' and click Next, when the Found New Hardware Wizard pops up.



Select @'Install from a list or specific location (Advanced)' and click Next .




3 Select ● 'Search for the best driver in these locations' and check the ✓ 'Search removable media (floppy, CD-ROM...)' and click Next .

If the 'driver is not found' message is displayed after clicking Next, click Back and the screen appears once again. Check the 'Include this location in the search' and designate the driver folder in the CL-S10w CD-ROM.

(Example) In the case the CD-ROM is in the E drive.

E: \driver



Click Finish .

5 Select **●** 'No, not this time' and click Next, when the Found New Hardware Wizard pops up.

After clicking Next, when the screen from Step 2 appears again, select (a) 'Install from a list or specific location (Advanced)' and click Next.


6 Select ● 'Search for the best driver in these locations' and check the ✓ 'Search removable media (floppy, CD-ROM...)' and click Next .

If the 'driver is not found' message is displayed after clicking **Next**, click **Back** and the screen appears once again. Check the **1nclude this location in the search** and designate the driver folder in the CL-S10w CD-ROM


(Example) In the case the CD-ROM is in the E drive.

E: \driver

**7** Click Finish.










## Check the COM port assigned to the photometer.

Select 'Control Panel' from the Start menu, select 'System', then select 'Device Manager' from the 'Hardware' tab and expand the 'Ports (COM & LPT)' to show the assigned COM port number.

#### Note

This COM port number is necessary to start CL-S10w and to connect the photometer.



The above installation is completed.

#### 3. Uninstallation of CL-S10w (Before version up)

Firstly uncheck the ✓ 'CI-S10w' from the Excel Add-Ins setting menu.

Perform installation step 9 to access the Add-ins setup screen.



2 Select the 'Control Panel' in the Start menu and double click on the 'Add/Remove Program' icon.

Select 'CL-S10w' from the 'Add/Remove Program' list and click on the Remove button.

## When using Windows 7, Excel 2007

The screens might differ from those in Excel 2010, but the steps are the same.

Please follow the steps below.

You will see a User Account Control dialog box during installation of the software. At that time, select "Yes" or "Continue".

#### 1. Installation


- Start Windows.
- 2 Set and insert the CL-S10w CD-ROM in the CD-ROM drive.
  The installation program should start up automatically. Please double-click on the 'Setup.exe' icon if the installation does not start automatically.
- 3 Select a language from the language dialog box and click OK.

  'Chinese' is in simplified form. When using Traditional Chinese OS, please select the 'English'.


We shall proceed and explain with the 'English' hence on.

The wizard screen will appear and click Next.






Fead the License Agreement and select (a) 'I accept the terms in the license agreement' if you agree to it and click Next .




## 6 Check the destination folder to install to and click Next.

The destination folder can be changed. Please remember the path of the destination folder as it is necessary during the Excel Add-Ins setup.



7 Click Install .
File copy will begin.




8 Click Finish when the installation is completed.




9 Next add CL-S10w into Excel Add-Ins. Start Excel 2007, click on the top left round icon and click Excel Options from the menu.



10 Select 'Add-Ins' on the left and click Go in the Manage Add-Ins below.



Click Browse from the Add-Ins setting menu.




12 Select the destination folder when CL-S10w is installed and select the CL-S10w. xla (the file extension might not be shown in some cases) and click OK.

(Example) C:\Program Files
\KONICAMINOLTA\CL-S10w



13 Check the 'CI-S10W' added in the Add-Ins setting menu and click OK.



14 "CL-S10W" was added to the "Add-Ins" in the menu bar in Excel 2007.



#### 2. Installation of the device driver


Connecting the instrument to a USB port of the PC requires the device driver to be installed. Please follow the steps below.

#### For CL-500A

Connect the instrument to a USB port of the PC.

The installation of the device driver should start automatically, and select the icon showing Installing device driver software from the taskbar.

Click on 'Skip obtaining driver software from Windows Update'.



Installing device driver software % X

Installing device driver

Close

N 🔁 🕩

Click here for status.


Glick Yes in the Confirmation window.



Wait for the screen below to appear and click Close.

Two kinds of device drivers for CL-500A will be installed.

The installation may take several minutes. Do not turn off the power of CL-500A or pull out the USB cable until the installation is complete.



## 5 Use the following procedure to heck that the device drivers are properly installed.

Right click on the 'Computer' from the Start menu and select 'Properties'.


The screen below will appear after clicking 'Device Manager' on the left of the Control Panel.


On this screen, make sure that "USB Composite Device" has properly been installed.

If the installation fails, the "USB Composite Device" may not be displayed on the screen or, even if the "USB Composite Device" is displayed, some devices may be located under the "Other devices" directory as shown in the figure below.

In such a case, uninstall the "USB Composite Device" and some devices under the "Other devices" directory; then perform the installation again from step 1.

The above installation is completed.





#### For CL-200A

With the CL-S10w installation CD-ROM inserted in the PC, connect the instrument to a USB port of the PC.

The installation of the device driver should start automatically, and select the icon showing Installing device driver software from the taskbar.

**2** Click on 'Skip obtaining driver software from Windows Update'.






Glick Yes in the Confirmation window.




Wait for the screen below to appear and click Close.

Please wait for a while as this may take several minutes.




Right click on the 'Computer' from the Start menu and select 'Properties'. Clicking on 'Device Manager' on the left of the Control Panel will open the screen as shown to the right.



6 Right click on 'FT232R USB UART' and select 'Update Driver Software'.



**7** Click on 'Browse my computer for driver software'.




Designate the driver folder in the CL-S10w CD-ROM and click Next.

(Example) In the case of CD-ROM in E drive.

E:\driver


G Click Close .




10 Select the icon from the taskbar like Step 1 as the USB Serial Port device driver will start installation automatically.

Click on 'Skip obtaining driver software from Windows Update' and click Yes in the Confirmation window.

Wait for the screen below to appear and click Close.






12 Show the Device Manager like Step 5 and right click on the 'USB Serial Port' and select 'Update Driver Software'.



13 Click on 'Browse my computer for driver software'.




Designate the driver folder in the CL-S10w CD-ROM and click Next.

(Example) In the case of CD-ROM in E drive.

E:\driver

15 Click Close .




## 16 Check the COM port assigned to the photometer.

Show the Device Manager like Step 5 and expand the 'Ports (COM & LPT)' to show the assigned COM port number.

#### Note


This COM port number is necessary to start CL-S10w and to connect the photometer.



The above installation is completed.

#### 3. Uninstallation of CL-S10w (Before version up)

> Please follow steps 9-10 to show the Add-Ins setting menu.



2 Select the 'Control Panel' in the Start menu and click on the 'Uninstalling the program' icon.

Select 'CL-S10w' from the 'Uninstalling or changing the program' list and click on the Uninstall button.

### When using Windows 8, Excel 2013

Be sure to use a 32-bit Excel even if the OS is a 64-bit version.

The setup procedure for Excel 2010 is the same as that for Excel 2013, though the screen layout may differ between these Excel versions.

Please follow the steps below.

You will see a User Account Control dialog box during installation of the software. At that time, select "Yes" or "Continue".

#### 1. Installation

Start Windows.

## 2 Set and insert the CL-S10w CD-ROM in the CD-ROM drive.

Click on "Tap to choose what happens with this disc." at the upper right of the screen.

Then click on 'Run setup.exe'.



Select a language from the language dialog box and click OK.

'Chinese' is in simplified form. When using Traditional Chinese OS, please select the 'English'.


We shall proceed and explain with the 'English' hence on.

The wizard screen will appear and click Next.






Read the License Agreement and select (a) 'I accept the terms in the license agreement' if you agree to it and click [Next].




6 Check the destination folder to install to and click Next.


The destination folder can be changed. Please remember the path of the destination folder as it is necessary during the Excel Add-Ins setup.




7 Click Install .
File copy will begin.




Click Finish when the installation is completed.




9 Adding CL-S10w into Excel Add-Ins: Start Excel 2013 and click on Options on the left menu.



Select 'Add-Ins' on the left and click Go in the Manage Add-Ins below.




Click Browse from the Add-Ins setting menu.



12 Select the destination folder when CL-S10w is installed and select the CL-S10w. xla (the file extension might not be shown in some cases) and click OK.

(Example) C:\Program Files \KONICAMINOLTA\CL-S10w

13 Check the ✓ 'CI-S10W' added in the Add-Ins setting menu and click OK.



14 "CL-S10W" was added to the "Add-Ins" in the menu bar in Excel 2013.



- \* When restarting Excel 2013 after installing CL-S10w as an add-in for the Excel, you may find that the add-in tab is missing. (In such a case, the Option screen will show that CL-S10w has been installed as an add-in.)
  - If the add-in tab is missing, set up the add-in again according to the following procedure:
- Perform add-in setup steps (9 to 12) again.
- 2 When clicking "OK" at step 12, you will see a message asking you to overwrite the setup. Click "OK" to overwrite the setup and click "OK" again to exit the screen.
- The add-in tab will be restored, and will not be missing after restarting Excel.

**Programs and Features** 

Power Options

#### 2. Installation of the device driver

Connecting the instrument to a USB port of the PC requires the device driver to be installed. Please follow the steps below.

#### For CL-500A

## Connect the instrument to a USB port of the PC.

Device driver installation will begin.

Two kinds of device drivers for CL-500A will be installed.

The installation may take several minutes. Do not turn off the power of CL-500A or pull out the USB cable until the installation is complete.


# 2 Use the following procedure to heck that the device drivers are properly installed.


Place the cursor at the lower left corner of the screen. When a window opens, rightclick. Select 'Device manager' on the menu. The screen as shown to the right will appear. On this screen, make sure that "USB Composite Device" has properly been installed.


If the installation fails, the "USB Composite Device" may not be displayed on the screen or, even if the "USB Composite Device" is displayed, some devices may be located under the "Other devices" directory as shown in the figure below.

In such a case, uninstall the "USB Composite Device" and some devices under the "Other devices" directory; then perform the installation again from step 1.

The above installation is completed.







#### For CL-200A


With the CL-S10w installation CD-ROM inserted in the PC, connect the instrument to a USB port of the PC.


Device driver installation will begin, and the task bar will show an icon named "Installing device driver software".

Place the cursor at the lower left corner of the screen. When a window opens, right-click.


Clicking on '**Device Manager**' will open the screen as shown to the right.














← ☐ Update Driver Software - FT232R USB UART

Browse for driver software on your computer


Search for driver software in this location:

Designate the driver folder in the CL-S10w CD-ROM and click Next.


(Example) In the case of CD-ROM in E drive.




6 Click Close.



7 Then, install the USB serial port device driver in the same manner as steps 2 to 6.





Device Manager

## Check the COM port assigned to the photometer.

Show the Device Manager like Step 2 and expand the 'Ports (COM & LPT)' to show the assigned COM port number.

#### Note

This COM port number is necessary to start CL-S10w and to connect the photometer.


File Action View Help

| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Help
| Image: Section View Hel

The above installation is completed.

#### 3. Uninstallation of CL-S10w (Before version up)

> Please follow steps 9-10 to show the Add-Ins setting menu.



Place the cursor at the lower left corner of the screen. When a window opens, right-click.

Select 'Program and function' on the menu.

Select 'CL-S10w' from the 'Program and function' list and click on the Uninstall button.

## About the template

Excel templates are installed together with CL-S10w.

The measurements in CL-S10w can be done immediately in these templates. Please use them for references when creating various templates for various use.

The templates are placed in the Template folder where CL-S10w is installed.

(Example) C:\Program Files\KONICAMINOLTA\CL-S10w\Template

In addition, select Start Menu -> All programs -> KONICAMINOLTA -> CL-S10w -> Template to start the template.


Please refer to the instruction manual for the details of the usage of the templates.

<Start Menu-> All programs -> KONICAMINOLTA -> CL-S10w -> CL-S10w Manual>

If you are using Windows 8, right-click on the start screen and select "All applications" at the lower right of the screen. You will see the template icons and the CL-S10w manual icon on the screen.

#### Measurement values trend


A time series chart with continuous variation in values is shown.



#### 2. A u'v' chroma diagram plot

The measured data are shown in a graph form in a u'v' chroma diagram.


The u'v' chroma diagram is an improved chroma diagram that compares the distance between the chroma points in the xy chroma diagram and the difference in the subjective color difference.



#### 3. Rank display


The rank is displayed in several separated regions of the xy chroma range.

With regards to the chroma of LED etc, whether there is a match among the various standards can be determined easily.




#### 4. Color Rendering Index

Color rendering indexes are shown visually for easy understanding.



#### 5. Spectral

Spectral irradiance data are displayed as the spectral waveform.




#### 6. Multi-point measurement

CL-200/CL200A allows multi-point measurement using multiple heads.

The multi-point measurement template is available in five types:

- 2-point measurement template containing the trend and xy chromaticity diagram
- 5-point measurement template containing the trend and xy chromaticity diagram
- 13-point measurement template containing the trend, xy chromaticity diagram and ANSI lumen measurements
- 30-point measurement template containing the trend and xy chromaticity diagram
- 30-point measurement template containing the ranking



#### 7. MacAdam ellipse and SDCM

This template shows the chromaticity variation of light sources as a MacAdam ellipse and SDCM (Standard Deviation of Color Matching).

